
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/9/2009
Test to be performed: Ground Condition: Dry ☑ Damp ☐ Wet ☐		Supervisor: JAW
Manhole_ID: S01CC1013MH	Test ID: <u>D1032-027041</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S01CC1013MH
0			Start of Survey	
0			Water Level	
11.10000038			Dye Test Visible	DYE SEEN AT JOINT
14.19999981			Dye Test Visible	DYE SEEN AT JOINT
17.89999962			Dye Test Visible	DTE SEEN AT JOINT
21.20000076			Dye Test Visible	DTE SEEN AT JOINT
30.70000076			Abandoned Survey	DYE TEST IS COMPLETE